


Untergeschloß



12.465




36 <sup>5</sup>	3.91 <sup>5</sup>	24	2.20	24	1.01	11 <sup>5</sup>	1.50 <sup>5</sup>	36 <sup>5</sup>
36 <sup>5</sup>	2.29	11 <sup>5</sup>	1.51	24	1.51	24	3.44 <sup>5</sup>	24
36 <sup>5</sup>	3.91 <sup>5</sup>	24	1.51	24	3.32	36 <sup>5</sup>		


PLEWA KAMIN

- 1 LÜFTUNG 12/18
- 2 HEIZUNG 18/18
- 3 OFFENER KAMIN 20/25





*fenster  
1/8 Grundfläche*



LGARAGE

ERDGESCHOSS

TERRASSE

FL. NR. 1371+1370 (TEILFLÄCHE)





UM OHNE  
RIEDUNG

WAAGRECHTE BOHLEN AN QUADRATROREN SOCKEL UND PFEILER AUS WASCHBETON

FL. NR. 605/31



Dachgeschoss



- 1 LÜFTUNG 12/18
- 2 HEIZUNG 18/18
- 3 OFFENER KAMIN 20/25

